# TEST REPORT

**Customer name** : KEEEN LIMITED
999 Biotechnology Factory Building- MAHIDOL UNIVERSITY, Puttamonthon 4 Road, Salaya, Puttamonthon, Nakhon Pathom 73170
Tel.: 02 747 1363-4 , 086 594 2772
Fax: 02 747 0120
E-mail: k.chaivet@keeen.co.th
Contact person: K. Kiattipong C.

| | | |
|---|---|---|
| Report no. | : | MTP/0436/2014 |
| Revision no. | : | 2 |
| Report date | : | 06-02-2014 |
| Sample received date | : | 21-01-2014 |
| Sample tested date | : | 22-01-2014 |
| Test completed date | : | 29-01-2014 |

**Sample description**

| | | |
|---|---|---|
| Sample name | : | Keeen Oil Spill Control |
| Sample no. | : | MTP/0436/2014-01 |
| Customer Reference | : | Lot No. 040913-016-030-3 |
| Sample submitted by | : | Customer |

| Test Item | Test Method | Unit | Results |
|---|---|---|---|
| Flash Point | ASTM D 93-11 | deg. C | See note |
| Hg | Acid Digestion , ICP-OES | mg/kg | Less than 0.01 |
| Se | Acid Digestion , ICP-OES | mg/kg | Less than 0.10 |
| As | Acid Digestion , ICP-OES | mg/kg | Less than 0.10 |
| Cr | Ashing , ICP-OES | mg/kg | Less than 0.10 |
| Ba | Ashing , ICP-OES | mg/kg | Less than 0.10 |
| Ni | Ashing , ICP-OES | mg/kg | Less than 0.10 |
| Zn | Ashing , ICP-OES | mg/kg | Less than 1.0 |
| Mn | Ashing , ICP-OES | mg/kg | Less than 1.0 |
| Cd | Ashing , ICP-OES | mg/kg | Less than 0.10 |
| Pb | Ashing , ICP-OES | mg/kg | Less than 0.10 |
| Cyanide | Water Extraction, Colorimetric | mg/kg | Less than 1 |

Remark : Precision parameters apply in determination of the above results and test methods. Also refer to ASTM D 3244-07 & IP Standard methods 367, Appendix E for utilization of test data to determine conformance with specifications. Results reported above relate only to the sample tested. This report shall not be reproduced except in full, without written approval of the laboratory and all works are carried out in accordance with our standard terms and conditions. Tests marked (**) are not under scope of accreditation.

Note : Can not test due to sample matrix.

Reviewed by _____
Thanakorn Tuntem
Assist Laboratory Manager

Approved by _____
Tirdsak Asurin
Laboratory Manager



**Intertek Testing Services (Thailand) Ltd.**
Head office : 60/1 Monririn Building, Suite 601 B, Soi Phaholyothin 8, Samsaennai, Phayathai, Bangkok 10400, Thailand.
Tel: +66 2 279 5040 (Auto 12 Lines) Fax: +66 2 270 1878-9 www.intertek.com
Map Ta Phut Laboratory : 22 Nernsamlee Road, Tambol Nernphra, Amphur Muang, Rayong Province 21150
Tel : +66 38 694 570-4 Fax : +66 38 694 558